

CAT. NO.
C058

EDP NO.
13058

CUTTER BAR AND HANDLE



BAND-IT®

BAND-IT-IDEX, INC.

A Unit of IDEX Corporation

P.O. Box 16307

Denver, Colorado 80216-0307 U.S.A.

1-800-525-0758

info@band-it-idx.com / www.band-it-idx.com

IDEX
IDEX CORPORATION

P06187

TO ASSEMBLE CUTTER BAR AND HANDLE

Place cutter bar into tool frame with cutter bar hole visible through slot of tool frame. Place friction spring into hole of cutter bar as shown below. Place cutter bar handle into hole of cutter bar and press down to compress spring until set screw hole is visible from side of cutter bar. Tighten set screw to complete assembly.

